

Flint Hills Resources, LP **Work Order Details**

Org: FHR-PE Site: PE

WO #: PE44151

WO Desc: R-17 manual M1 valve packing needs tightned. Small leak at packing when partially opene.

Parent WO#:

WO Long Desc:

Location: E-R-17 **REACTOR 17** WO Priority: 1

Asset: 1347996

REACTOR 17

Asset Service:

Entry Date: 4/4/2013

WO Status: CLOSE

Action Code: LDAR

Project #:

Originator: DAN BUCK

Status Date: 10/2/2013

Work Type: CM

Failure Class: VSSL

Job Plan:

Planned Start:

Actual Start: 4/4/2013

Review Date:

PM/Bundle:

Planned Completion:

Actual Completion: 4/4/2013

Plant Information

RC: PERC01 When Code: RT

Planner: WILLIAM STONEKING

MOC#: **MOC Status:**

P&ID:

Lead Craft: MECH

MOC Desc:

SIR/EIS Required:

LDAR

Tag #:

Size:

1st Attempt Made:

LDAR Planning Notes: LDAR Additional Notes:

Leak Type:

1st Attempt Was: 1st Attempt Due By: 4/9/2013

After 1st Attempt PPM:

Leak Location: **Location Orientation:**

Final Due By: 4/19/2013

Work Order Notes

JOSEPH VITTONE

04/04/2013 Tightened packing.

Completed by Emp #:

Signature:

1 /